



CLAMP ON EARTH TESTER FT6380

Field Measuring Instruments





0.02 Ω to 1600 Ω wide measurement range for earth resistance measurement 1.00 mA to 60.0 A covering small leakage current to load current

For multi grounded systems only











High Accuracy

Get Things Done with Super Slim Jaws

Easy clamping!

Open jaws easily with just two fingers. Only half the grip power is needed compared to typical clamp earth testers.



0.87 inch



Clamp at the narrowest point!

Now you can easily clamp the earth cable on the pole without digging. The dramatically slim 0.79 inch (20mm) jaws let you finish your job easily and efficiently.



0.79 inch

(20 mm) 1.5 inch 0.87 inch (38 mm) (22 mm)

LCD with beautiful back light

With the bright back light, you can easily read the measurement value even in dark locations.



You can store up to 2,000 measurement values in the field and recall them in your

Memory number

Alarm Function

Set the alarm to audibly and visually notify yourself that the resistance or current value exceeds the threshold.

Large storage capacity (up to 2,000 data)

office later.

Filter function enables even more accurate measurements

Resistant mode filter: digital filter gives you steadier readings.

Current mode filter: Low-pass filter eliminates harmonics current over 180Hz.



Quick Start!

No wait time after powering on. Start measuring instantly without zerocalibration.


High Accuracy and Repeatability

Well-designed magnetic shields eliminate the leakage flux between the two cores that

often affect measurement accuracy.

Measurement Principle

FT6380 can measure Multi-Grounded systems.



Clamp on the earth cable. The instrument has two cores for voltage injection and current measurement.


- 1. The voltage transducer injects a defined voltage into the multi-grounded system.
- 2. From the defined voltage and measured current, the total circuit loop resistance is calculated in the following equation.

$$Rx + \frac{1}{\frac{1}{R_1} + \frac{1}{R_2} + \frac{1}{R_3} + \frac{1}{R_4} + \cdots} = \frac{V}{I}$$

In a typical multi-grounded system, the parallel resistance value is small enough to be ignored and the equation as referred on the left can be simulated as follows.

$$Rx = \frac{V}{I}$$


Measurement Examples





In multi-grounded system, the larger the number of grounding poles, the more accurate the measured value. Where the number of grounding poles are few, if just only one carries a very small resistance (e.g., $1\Omega)$, the measured value will be close to the true value. On the other hand, poles with large resistances (e.g., $100\Omega)$ will result in greater measurement uncertainties.



* The illustration may differ slightly from the field application.







Display	Digital/ LCD, max. 2000 digits Display update rate: 2 times / s		
Range switching	Auto-range		
Maximum conductor diameter for measurement	ø 32 mm (1.26 in)		
Power supply	LR6 alkaline battery × 2 Continuous operating time: Approx. 35 hours With display backlight off		
Auto power save	Power save state when 5 minutes have elapsed since the last operation		
Operating temperature and humidity	-10°C (14°F) to 50°C (122°F), 80 % rh or less (non-condensation)		
Storage temperature and humidity	numidity -20°C (-4°F) to 60°C (140°F), 80 % rh or less (non-condensation, except for the battery)		
Dustproof and waterproof	IP40 (EN60529) With Jaws Closed		
Maximum rated voltage to earth	600 VAC measurement category IV (anticipated transient overvoltage 8000 V)		
Dielectric strength	Between the Case and the Clamp core 7400 Vrms 1 minute		
Maximum input current	100 A AC continuous, 200 A AC for 2 minutes (50/60 Hz)		
Conductor position effects	Within ±0.5% rdg. (using the center of the sensor as the reference, in all positions)		
Magnetic field interference	10 mA or less in an external magnetic field of 400 A/m at 50/60 Hz AC		
Applicable standards Safety: EN61010 EMC: EN61326			
Dimensions, Mass	Approx. 73 mm (2.87 in) W × 218 mm (8.58 in) H × 43 mm (1.69) D, Approx 620 g (21.9 oz)		
Accessories	Carrying Case×1, Resistance Check Loop×1, Strap×1, Instruction Manual×1, Alkaline Battery(LR6)×2		

Resistance mode

Accuracy guaranteed for 1 year, Temperature and humidity

for guaranteed accura	cy:23±5°C	80%rh or	less (no	condensation)

Range	Measurement Range	Resolution	Accuracy
0.20 Ω	$0.02~\Omega$ to $0.20~\Omega$	0.01 Ω	±1.5 % rdg. ±0.02 Ω
2.00 Ω	$0.18~\Omega$ to $2.00~\Omega$	0.01 Ω	±1.5 % rdg. ±0.02 Ω
20.00 Ω	1.80 Ω to 20.00 Ω	0.01 Ω	±1.5 % rdg. ±0.05 Ω
50.0 Ω	$18.0~\Omega$ to $50.0~\Omega$	0.1 Ω	±1.5 % rdg. ±0.1 Ω
100.0 Ω	50.0 Ω to 100.0 Ω	0.1 Ω	±1.5 % rdg. ±0.5 Ω
200.0 Ω	100.0 Ω to 200.0 Ω	0.2 Ω	±3.0 % rdg. ±1.0 Ω
400 Ω	$180~\Omega$ to $400~\Omega$	1 Ω	±5 % rdg. ±5 Ω
600 Ω	400 Ω to 600 Ω	2 Ω	±10 % rdg. ±10 Ω
1200 Ω	600 Ω to 1200 Ω	10 Ω	±20 % rdg.
1600 Ω	1200 Ω to 1600 Ω	20 Ω	±35 % rdg.

Alarm function

	Separate Hi/Lo settings for resistance measurement	
Alarm Hi/Lo	and current measurement	
	Resistance measurement: Hi.AL/Lo.AL	
	Current measurement: Hi.AL/Lo.AL	
	Resistance measurement: 0.02Ω to $1,600 \Omega$	
Alarm threshold setting range	Resistance measurement initial value: 25.0 Ω	
	Current measurement: 0.05 mA to 200.0 mA,	
	0.201 A to 60.0 A	
	Current measurement initial value: 1.00 mA	

Frequency of measurement Approx. 2,400Hz.

Current Mode

Accuracy guaranteed for 1 year

Temperature and humidity for guaranteed accuracy:23±5°C 80%rh or less (no condensation)

Range	Measuerment Range	Resolution	Frequency Range	Accuracy		
				Filter off	Filter on	
20.00 mA	1.00 mA to 20.00 mA	0.01 mA	$45 \le f \le 66$ Hz	±2.0 % rdg. ±0.05 mA	±2.0 % rdg. ±0.05 mA	
20.00 IIIA			$30 \le f < 45$ Hz, $66 < f \le 400$ Hz	±2.5 % rdg. ±0.05m A	_	
200.0 mA	0.0 mA 18.0 mA to 200.0 mA	0.1 mA	$45 \le f \le 66$ Hz	±2.0 % rdg. ±0.5 mA	±2.0 % rdg. ±0.5 mA	
200.0 IIIA	18.0 IIIA 10 200.0 IIIA		$30 \le f < 45Hz, 66 < f \le 400Hz$	±2.5 % rdg. ±0.5m A	_	
2.000 A	0.180 A to 2.000 A	0.001 A	$45 \le f \le 66$ Hz	±2.0 % rdg. ±0.005 A	±2.0 % rdg. ±0.005 A	
2.000 A	0.160 A to 2.000 A		$30 \le f < 45$ Hz, $66 < f \le 400$ Hz	±2.5 % rdg. ±0.005 A	_	
20.00 4	20.00 A 1.80 A to 20.00 A	0.01 A	$45 \le f \le 66$ Hz	±2.0 % rdg. ±0.05 A	±2.0 % rdg. ±0.05 A	
20.00 A			$30 \le f < 45$ Hz, $66 < f \le 400$ Hz	±2.5 % rdg. ±0.05 A	_	
60.0 A	18.0 A to 60.0 A	0.1 A	$45 \le f \le 66$ Hz	±2.0 % rdg. ±0.5 A	±2.0 % rdg. ±0.5 A	
00.0 A			$30 \le f < 45$ Hz, $66 < f \le 400$ Hz	±2.5 % rdg. ±0.5 A	_	

Accessories

Carrying Case





Resistance Check Loop



Note: Company names and Product names appearing in this catalog are trademarks or registered trademarks of various companies.

HIOKI E.E. CORPORATION

HIOKI (Shanghai) Sales & Trading Co., Ltd.:
TEL+86-21-63910300 FAX+86-21-63910360
http://www.hioki.cn / E-mail: info@hioki.com.cn
Beijing Office: TEL+86-10-84418761
FAX+86-10-84418763 / E-mail: info-bj@hioki.com.cn
Guangzhou Office: TEL+86-20-38392673
FAX+86-20-38392679 / E-mail: info-gz@hioki.com.cn
Shenzhen Office: TEL+86-755-83038357
FAX+86-755-83039160 / E-mail: info-sz@hioki.com.cn Headquarters:
81 Koizumi, Ueda, Nagano, 386-1192, Japan
TEL +81-268-28-0562 FAX +81-268-28-0568
http://www.hioki.co.jp / E-mail: os-com@hioki.co.jp

HIOKI USA CORPORATION:
TEL +1-609-409-9109 FAX +1-609-409-9108
http://www.hiokiusa.com / E-mail: hioki@hiokiusa.com

Guangzhou Office: TEL +86-20-38392673
FAX +86-20-38392679 / E-mail: info-gz@hioki.
Shenzhen Office: TEL +86-20-38392679 / E-mail: info-gz@hioki.
Shenzhen Office: TEL +86-20-38392679 / E-mail: info-gz@hioki.
Shenzhen Office: TEL +86-20-38392673
FAX +86-20-38392679 / E-mail: info-gz@hioki.
Shenzhen Office: TEL +86-20-38392673
FAX +86-20-38392679 / E-mail: info-gz@hioki.
Shenzhen Office: TEL +86-20-38392673
FAX +86-20-38392679 / E-mail: info-gz@hioki.
Shenzhen Office: TEL +86-

DISTRIBUTED BY